



13 March 2015

To: Recipients of M43-A
From: Jennifer K. Adams, MT(ASCP), MSHA
Subject: Error in Section 7.6 in M43-A

This notification is to inform you of an error in Section 7.6 (step #6) in CLSI document M43-A, *Methods for Antimicrobial Susceptibility Testing for Human Mycoplasma; Approved Guideline*.

Step #6 in Section 7.6 reads: “Add 0.175 mL of the desired dilution of the inoculum in wells 1–9, 11, and 12. Well 12 serves as the growth control. Start with well 12 and work backwards to well 1 to prevent drug carryover. Add 0.175 mL of the appropriate uninoculated medium to wells 10 and 11 (total of 0.2 mL) for media and drug controls.”

This text is incorrect and has been corrected as shown in the highlighted text below:

6. Add 0.175 mL of the desired dilution of the inoculum in wells 1–8 and 12. Well 12 serves as the growth control. Start with well 12 and work backwards to well 1 to prevent drug carryover. Add 0.175 mL of the appropriate uninoculated medium to wells 9, 10, and 11 (total of 0.2 mL) for solvent, media, and drug controls.

If you require any additional clarification regarding this correction, please contact CLSI Customer Service (customerservice@clsi.org).

We appreciate your commitment to CLSI, and regret any inconvenience.